

## Calibration modes for the Chattanooga equipment



**Transport**  
with Unit on, hit the folder button,  
then hold down intensity down and time down until  
beep.



**XT and vectra genesis**  
two top right hand buttons, during power up start.



**Vectra 4C**  
With unit on, hold the home button for 3 seconds to  
get to next screen  
Then hold the folder button for three seconds to get  
to the cal screen, be careful in this  
area, memory can be corrupted with the push of a  
button, unit could be disabled.